## CLIPPER ADVENTURER 9/10/01 DETAILS OF INSPECTION VIOLATIONS

NO.	LOCATION	REF.	POINTS	CRITICAL	DESCRIPTION
1	POTABLE WATER	*	0	No	
THE POTABLE WATER SYSTEM OPERATIONS, MAINTENANCE, AND RECORD KEEPING WERE EXCELLENT.					
2	POTABLE WATER	07	0	Yes	
THE IN	ITERNATIONAL SHORE CONNECTION FOR FIRE FIGHTING WAS NOT FITTED WITH A	BACKFLO	OW PREVENTE	ER.	
I will contact the Chief Engineer for sizing and we will provide an RPZ to the vessel that can be installed when hooking up the international shore connection. A system for testing RPZ's is already established on board.					
3	CREW MESS	36	0	No	
LIGHT LEVELS ALONG THE SERVICE LINE MEASURED 3 FOOT CANDLES.					
4	MAIN GALLEY	19	0	No	
BLOCK	S OF CUT CHEESE WERE NOT LABELED.				
5	PROVISIONS	19	0	No	
GREY WATER PIPES WITH FLANGES AND COMPRESSION FITTINGS WERE FOUND ABOVE FOOD PRODUCTS IN THE DRY STORE AREAS.					
Noted. Preliminary plans for renewing this space have been made. Final plans and timing for renovation are still pending.					
6	PROVISIONS	33	1	No	
BULKHEADS AND DECKHEADS IN THE DRY STORES CONTAINED EXPOSED PIPING, WIRING, PAINTED SURFACES, LEDGES, AND OTHER NON-EASILY CLEANABLE FEATURES.					
Noted	. See above.				
7	FOOD SERVICE-GENERAL	*	0	No	
OVERALL, FOOD HANDLING, CLEANLINESS, TEMPERATURE CONTROLS, AND GENERAL KNOWLEDGE OF EMPLOYEES WAS EXCELLENT.					
8	CORRECTIVE ACTION STATEMENT	*	0	No	
IN DEVELOPING THE CORRECTIVE ACTION STATEMENT FOR THIS INSPECTION, CRITICAL-ITEM DEFICIENCIES (DESIGNATED WITH YES IN					
CRITICAL COLUMN (WORTH 3 - 5 POINTS), WHETHER DEBITED OR NOT, SHOULD INCLUDE STANDARD OPERATING PROCEDURES AND					
MONITORING PROCEDURES IMPLEMENTED TO PREVENT THE RECURRENCE OF THE CRITICAL DEFICIENCY.					
PREPARE CORRECTIVE ACTION STATEMENT AS A WORD PROCESSING OR SPREADSHEET FILE WHICH WILL BE SENT TO USPHS / VSP AS AN					
EMAIL MESSAGE ATTACHMENT. PLEASE EMAIL CORRECTIVE ACTION STATEMENT TO: VSP@CDC.GOV					
USE EMAIL MESSAGE SUBJECT LINE: SHIP NAME - CAS - [INSERT INSPECTION DATE].					